

OIL SPILL RESPONSE

Giolee Global Resources Limited was contacted by **SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED** to carry out Containment/Recovery and Evacuation of Crude Oil at **12" IMO RIVER PIPE LINE AT OWAZA**. The contract execution started on the 18 of September, 2016 and ended on the 28th of October, 2016. Mechanical recovery method was used to evacuate the oil from the borrow pit to a vacuum truck.



Fig. 1: Initial Look Showing Spill Point unrecovered Crude Oil



Fig 2: Borrow Pit with unrecovered Crude Oil



Fig 3: Mopping of Residual oil deft point.



Fig 4: Repairs Ongoing on the deft point



Fig 5. Back filling of excavated spill point



Fig 6: Recovery from a Borrow Pit



Fig 7: Vacuum Truck Evacuating Crude Oil from a Borrow Pit



Fig 8: Mechanical recovery



Fig 9: Vacuum Truck Evacuating Crude Oil