

## CLEAN-UP ALONG 18" TEBIDABA/BRASS PIPELINE, BENIKRUKRU, SOUTHERN IJAW LGA, BAYELSA STATE

Glolee Global Resources Limited was commissioned by **NAOC** to carry out clean up of crude oil impacted area along 18" Tebidaba/Brass Pipeline at **Benikrukru**, in Southern Ijaw Local Government Area of Bayelsa State to prevent further impact on the affected area in line with environmental regulations and best practices.

The impact is confined within the AGIP right of way, with the area inundated by tides from the adjoining river.

In line with the project objective and scope, the impacted area is free from visible oil sheen.

All activities were carried out in compliance to regulatory guidelines and NAOC standards and procedures.



**Plate 2.1: Site overview before clean up  
Showing stressed vegetation and sheen**



**Plate 2.2: Overview of the Site after work.**



**Plate 3.1: Showing the Induction of  
Workers at the site**



**Plate 3.2 Clearing of stressed vegetation at the site**



**Plate 3.3: Scrapping of the impacted soil at site**



**Plate 3.4: A Section of the site after scraping of stained oil**



**Plate 4.1: Breaking of soil lumps around the Spill point.**



**Plate 4.2: Scrapping of under laid dead vegetation**